



Run-off creating waterfalls
behind lots 13, 14 & 15

NOTE THE WATERFALL
RUNOFF COMING FROM
WOODS



Flooding on the sidewalk in front of Lot 17



Flooding behind Lot 10 –
Wood property to the left
side behind the wall



Flooding in courtyard of Lot 10 (also flooded inside this house)



Run-off spilling over retaining wall coming from Wood property



Flooding behind
Lots 13-17
Wood property is
on the left side
behind the berm



Flooding between
Lots 13 and 14



Flooding alongside Lot 17



In ground pop-ups
overwhelmed by flooding

Flooding behind lots
11 - 15





Water level up to top of retaining wall

Flooding in courtyard
of Lot 9





Next day – erosion
behind Lot 12

**EROSION CAUSED BY
RUNOFF FROM WOODS
PROPERTY**

Accumulated mud/clay runoff from erosion of the slope behind lots 11 – 15 coming from Wood property





Accumulated mud/clay runoff from erosion of the slope behind lots 11 – 15 coming from Wood property



Note No Parking signs on both sides of Greenway Landing due to the narrowness of the road



Note No Parking signs on both sides of Greenway Landing