



DRAFT

N. Columbia Street



NOT TO SCALE

LEGEND

- = BACKGROUND COMMITTED OR RECOMMENDED IMPROVEMENT
- = APPLICANT IMPROVEMENT
- = NECESSARY IMPROVEMENT

MONITOR FOR SIGNALIZATION

NO RIGHT-TURNS

LINK ROSEMARY APARTMENTS SITE

E. ROSEMARY PARKING DECK

West Rosemary Street

RE-OPTIMIZE SIGNALS

Recommend Opposite Driveway Direction Compared to Site Plans

Raised Delineators to Prevent Left-Turns

West Franklin Street

East Franklin Street

S. Columbia Street



Link Rosemary Apartments Transportation Impact Analysis

COMMITTED & RECOMMENDED IMPROVEMENTS

HNTB **DATE: January 2022**

FIGURE ES-3