

Project Summary

Overview

Site Description				
Project Name	11SIXTY5 Weaver Dairy Road			
Address	1165 Weaver Dairy Road			
Property Description	86,412 sq. ft. (1.98 acres)			
Existing	Vacant land (previous site of Montessori School)			
Orange County Parcel Identifier Numbers	9880-35-0595			
Zoning	Mixed Use-Office/Institutional-1 (MU-OI-1)			
	Office/Institutional-3 (OI-3)			

Development Intensity				
Topic	Comment			
Use/Density (Sec 3.7)	Office, retail, and medical clinic	\bigcirc		
Dimensional Standards (Sec. 3.8)	No setbacks required; proposing 19' street setback, 7' interior setback, and 30' solar setback.	⊘		
Floor area (Sec. 3.8)	Maximum: 48,909 sq. ft. Proposed: 48,324 sq. ft.	\odot		
Modifications to Regulations (Sec. 4.5.6)	landscape buffers on north, west, and east property lines; steep slopes	М		
Adequate Public Schools (Sec. 5.16)	Not applicable	N/A		
Inclusionary Zoning (Sec. 3.10)	Not applicable	N/A		
Landscape				
Buffer - North (Sec. 5.6.2)	30' External Type "D"			
Buffer – East (Sec. 5.6.2)	10' Internal Type "B"	M		
Buffer – South (Sec. 5.6.2)	10' Internal Type "B"	\odot		
Buffer - West (Sec. 5.6.2)	10' Internal Type "B"	M		
Tree Canopy (Sec. 5.7)	Minimum 30% canopy			
Landscape Standards (Sec. 5.9.6) Constructed to Town standards		\odot		
Environment				
Resource Conservation District (Sec. 3.6)	Not applicable	N/A		

Erosion Control (Sec. 5.3.1)	More than 1 acre of land disturbance proposed; Performance bond required.			
Steep Slopes (Sec. 5.3.2)	Slopes in easement appear to be manmade- 5,735 sq. ft. steep slopes to be removed >25%.			
Stormwater Management (Sec. 5.4)	Underground Stormwater treatment measure	000		
Land Disturbance	83,200 sq. ft. (106% of net land area, includes off-site work)	Ø		
Impervious Surface (Sec. 3.8)	58,219 sq. ft. (74% of net land area)			
Solid Waste & Recycling	Private trash pickup; County recyclable pickup			
Jordan Riparian Buffer (<u>Sec. 5.18</u>)	Not applicable	N/A		
Access and Circula	tion			
Road Improvements (Sec. 5.8)	None	\odot		
Vehicular Access (Sec. 5.8)	Improved curb cut on Weaver Dairy Road; Rear parking garage access from adjacent easement on west property line			
Bicycle Improvements (Sec. 5.8)	Signage at entrance "Covered bike parking in deck"	\odot		
Pedestrian Improvements (Sec. 5.8)	Improved 5-foot concrete sidewalk with accessible ramp; accessible plaza along building frontage; warning sign and LED lights to be added to existing crosswalk across Weaver Dairy Rd.	②		
Traffic Impact Analysis (Sec. 5.9)	Monitor and retime NC 86 and Weaver Dairy Road intersection; Cross-access with Weaver Crossing; Pedestrian warning signage at driveway; Additional access point for one-way drive.	⊘		
Vehicular Parking (Sec. 5.9)	lar Parking 231 spaces total, including 14 handicap spaces, with 12			
Transit (Sec. 5.8)	nsit			
Bicycle Parking (Sec. 5.9)	24 total proposed spaces (2 in plaza, 10 in parking deck, 12 in lockers in parking deck)			
Parking Lot Standards (Sec. 5.9)	Built to Town standards	⊗ ⊗		
Technical				
Fire	Full fire flow study and report will be provided during the ZCP phase			
Site Improvements	Driveway access and connection to adjoining Weaver Crossing property	②		
Schools Adequate Public Facilities	Not applicable	N/A		

(<u>Sec. 5.16</u>)		
Recreation Area (Sec. 5.5)	Not applicable	N/A
Lighting Plan (Sec. 5.11)	0.3 foot-candles at property line	
Homeowners Association (Sec. 4.6)	Not applicable	N/A

Project Summary Legend

Symbol	Meaning	Symbol	Meaning
\odot	Meets Requirements	CDC	Community Design Commission
М	Seeking Modification	НАВ	Housing Advisory Board
С	Requires Council Endorsement	ТСАВ	Transportation and Connectivity Board
FP	Required at Final Plan;	ESAB	Environmental and Sustainability Board
NA	Not Applicable	ocsw	Orange County Solid Waste
PC	Planning Commission	NCDOT	North Carolina Department of Transportation