


Application for Conditional Zoning


South Columbia Street Annex

1150 S. Columbia Street

Transportation and Connectivity Advisory Board
September 22, 2020




Town of Chapel Hill | 405 Martin Luther King Jr. Blvd. | www.townofchapelhill.org




Overview

- Mixed Use Building
 - 6-story
 - Apartment Units
 - Office Spaces
- Approximately 4 Acres
- Existing Use:
 - Vacant / Wood
 - Monroe Street ROW



Site details Vehicular Access

- Full Access
 Driveway
- Abandonment of Existing Right-of-Way




Site details Roadway Improvements

- Addition Northbound Left-Turn Lane
- Existing Median Removed


Bicycle Improvements

Striping Along Frontage



Site details Pedestrian Improvements

- Sidewalks
- ADA Ramps
- RRFB Signal
- CrosswalksVehicular Parking
- 69 Spaces
 - 3 Van Spaces
 - 21 Standards
 - 45 Underground



Site details Bicycle Parking

19 Spaces


Parking Lot Standard

 Built to Town's Standards

Traffic Impact Analysis

- Completed
 - Will Be Revised


Traffic Impact Analysis



Traffic Impact Analysis (continued)

Intersections	Peak	2014 Existing		2017 No-Build		2017 Build	
	Hour	LOS	Delay	LOS	Delay	LOS	Delay
NC 86 (S. Columbia St.) & Purefoy Road	AM	D	27.0	D	29.4	D	30.1
	NOON	С	15.3	С	16.1	С	16.4
	PM	Е	36.1	Е	42.5	Е	44.4
NC 86 (S. Columbia St.) & NC 54 Bypass Westbound Ramps	AM	С	27.0	С	22.8	С	22.8
	NOON	С	23.6	С	21.5	С	21.6
	PM	E	68.9	D	52.7	D	52.8
US 15-501 & NC 54 Bypass Eastbound Ramps	AM	C	34.4	С	24.6	С	24.6
	NOON	Α	9.9	В	11.6	В	11.6
	PM	F	93.0	В	15.2	В	15.2
NC 86 (S. Columbia St.) & Site Driveway*	AM	N/A	N/A	N/A	N/A	C*	21.1*
	NOON	N/A	N/A	N/A	N/A	B*	14.8*
	PM	N/A	N/A	N/A	N/A	D*	28.2*

Traffic Impact Analysis (continued)



- Recommendations
 - Retime the NC 54 Bypass
 Interchange Intersections
 Signals
 - Provide Additional Storage
 Capacity for NC 54 Bypass
 Westbound Off-Ramp
 - Consider Realigning the Proposed Driveway with Purefoy Road

Process

Town Evaluation of Application According to Standards

Report Presented to Advisory Boards and Commissions

Report Presented to Public Hearing: Report and Recommendation Presented to Town Council

Report Presented to Advisory Boards and Commissions

Report Presented to Town Council

Site Overview: Access and Circulation

Design/LUMO Standards	Comment	Status
Sec 5.8 Road Improvements	Additional Left-Turn Lane	

Site Overview: Access and Circulation

Design/LUMO Standards	Comment	Status
Sec 5.8 Vehicular Access	Abandonment of Existing Monroe Street ROW, Full Access Driveway, Northbound Left-Turn Lane	
Sec 5.8 Bicycle Improvements	Striping along the frontage	√

Site Overview: Access and Circulation (continued)

Design/LUMO Standards	Comment	Status
Sec 5.8 Pedestrian Improvements	Install ADA Ramps, Activated LED Signal, Crosswalk	✓
Sec 5.9 Vehicular Parking	69 Spaces	

Site Overview: Access and Circulation (continued)

Design/LUMO Standards	Comment	Status
Sec 5.9 Bicycle Parking	19 Parking Spaces	
Sec 5.9 Traffic Impact Analysis	TIA was completed, Will be revised at ZCP stage	√

Site Overview: Access and Circulation (continued)

Design/LUMO Standards	Comment	Status
Sec 5.9 Parking Lot Standards	Built to Town's standards	√

Recommendation to Town Council

- Approval
- Approval with Conditions
- Denial