



SCREENING INCREASE WITH ADDITIONAL SLATS – ALL
REPAINTED TO SHERWIN WILLIAMS HOT COCOA SW 6047

REPAINT EXISTING SPLIT – FACE CMU WATER
TABLE TO ORIGINAL COLOR



SCREENING INCREASE WITH ADDITIONAL SLATS – ALL REPAINTED TO SHERWIN WILLIAMS HOT COCOA SW 6047

REPAINT EXISTING SIDING TO ORIGINAL COLOR

REPAINT EXISTING SPLIT –FACE CMU WATER TABLE TO ORIGINAL COLOR





SCREENING INCREASE WITH ADDITIONAL SLATS – ALL REPAINTED TO SHERWIN WILLIAMS HOT COCOA SW 6047

REPAINT EXISTING SIDING TO ORIGINAL COLOR

REPAINT EXISTING SPLIT-FACE CMU WATER TABLE TO ORIGINAL COLOR

STARBUCKS COFFEE
EASTGATE CROSSING
CHAPEL HILL, NC





STARBUCKS COFFEE
EASTGATE CROSSING
CHAPEL HILL, NC

