

PAGE # OF PHOTO	PHOTO TO BE REPLACED	WHY REPLACE THIS PHOTO?	SUBSTITUTE PHOTO	WHY SUBSTITUTE THIS PHOTO?	PHOTO CREDIT
26	Modernist House	Poor example	None	The text adequately describes this area- just delete the photo.	No photo with this
54	Garage- i	Is not typical	Garage-2-021	Early 20 <sup>th</sup> cent. Garages are scaled more like this one	Kyser
72	Metal Roof	Too much baggage	Senlac Image 0450	Shows a clean new metal roof	Steifbold
111	Only photo on page	• Too much focus on attached garage	Friday House photo	This is really nice new construction in the district	Kyser or Stiefbold, Hooper Lane 0474
115	New Const. on a hill	Poor fenestration match	•	Could not find a photo by deadline	•
119	New cottage	Structure was Denied a COA	McCauley 0389	This cottage probably received a COA	Stiefbold
116	Text change	•	•	All houses in Gimghoul are not 2 sty, only some are.	•
123	Text change	•	•	ID photo as a sorority	•
128	Garage photo	Early 20 <sup>th</sup> cent Garages are typically small	Garage 3-19-21	This small garage is more consistent with form, height and scale of existing older garages.	Kyser
129	No change	•	•	•	•
132	No change	•	•	•	•
•	•	•	•	•	•
•	•	•	•	•	•

•