



Roof Scope Overview  
Granville Towers East Building HVAC Replacement




Public Way View (Far Side of Carolina Square Courtyard)

Granville Towers East Building HVAC Replacement



Public Way View (Near Side of Carolina Square Courtyard)

Granville Towers East Building HVAC Replacement



Carolina Square  
Building C

Guardrail is not visible  
as the building is approached

Granville Towers  
East Building