

# **KIM LEVELL DESIGN**

# 510 Hopper Lane | Certificate of Appropriateness

Version 1.0 – Issued 13th May 2021

#### CONTENTS

- Project Overvi
- Site Survey
- Site Location
- Site Context
- Site Context –
- Site Plan Exist
- Drainage & Sto
- Existing Condit
- New Landscap
- New Brick wall
- New Brick wall
- Materials and
- Perspectives &

iew	01
	02
	03
	04
Neighbouring Buildings	05
ting Conditions	06
orm Water Plan	07
tions Pictures - Part 1	08
tions Pictures - Part 2	09
tions Pictures - Part 3	10
tions Pictures - Part 4	11
tions Pictures - Part 5	12
pe Layout Plan - Site	13 14
I & Brick Stairs Layout	14
I & Brick Stairs – Execution Pictures	15
Finishes	17
& New Layout Plan	18

Project Overview




The scope of the project includes minor modification of the existing landscaping and restoration of original architectural features of its design.


The project scope is comprised of demolition of an existing brick parking pad and concrete slate, installation of a semi-permeable brick paver walkway, semipermeable chapel hill gravel landscaping area, installation of a reinforced concrete block wall with new drainage system to the front entrance, change finish, replace gutters, change roof tiles, add lighting and landscaping features.

All works on this site, including style and deign are to preserve structural integrity of the property.

Survey Plan




\*



Site Location



**SITE** | 510 Hooper Lane, Chapel Hill, NC




0.03 44

8LDY

0.01

Site Context





Site Context – Neighbouring Buildings



Reference 2 | Brick Stars Walkway - 303 E Franklin St





Reference 4 | Brick Finishes and Patterns - 521 Hooper Lane



Reference 5 | Painted Brick - 515 Senlac Rd






Reference 6 | Old East Building



Reference 7 | - Stucco Façade Treatment - New East Building








Reference 9 | 519 Hooper Lane





| 05

Site Plan - Existing Conditions












#### Stormwater & Drainage



The Topographic image depicts the water runoff from Battle Lane that is directed towards Hooper Lane, not only does debris collect adjacent to the property, but it is then forced down the original grade into the basement where the water was pumped into a rear swale. The new amendments allow for the stormwater to travel down the driveway of 510 Hooper Lane into the backyard.




Drains that was Installed on front wall to allow stormwater inside the building into the basement (Red Arrows)

Drainage | 510 Hooper Lane, Chapel Hill, NC


Image 2 - Evidence of Debris Acumulation on Hooper Lane adjacent to 510 Hooper Lane














Area where soil is collapsing - Water runs into the space during every storm and is heavy during heavier times. It is now just starting washing in.



never dries out.



Existing Conditions Pictures - Part 3



Existing Conditions Pictures - Part 4






| 11











New Landscape Layout Plan - Site





New Brick wall & Brick Stairs Layout



SCALE: 3/8" : 1'

| 14

New Brick wall & Brick Stairs – Execution Pictures



Perspectives



Perspective 2 | New Landscape

Perspective 3 | Front Door





Materials and Finishes



Reference 1 | Chapel Hill Gravel



Reference 3 | Front Door





Reference 2 | Copper Gutters





Reference 6 | Lighting



Perspectives & New Layout Plan




Perspective 2 | New Landscape







Perspective 4 | New Brick wall & Brick walkway



Layout | New Landscape Layout Plan